
Section 22 Connecticut

Appendix S

Connecticut Coastal Structures Inventory Study - Phase III

January 1990



**US Army Corps
of Engineers**
New England Division

REPORT DOCUMENTATION PAGE			Form Approved OMB No. 0704-0188	
<small>Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188), Washington, DC 20503.</small>				
1. AGENCY USE ONLY (Leave blank)		2. REPORT DATE January 1990		3. REPORT TYPE AND DATES COVERED Section 22
4. TITLE AND SUBTITLE Section 22, Connecticut Coastal Structures Inventory Study, Phase III, Appendix S, Glenville Quadrangle, Records of Structures With Photographs			5. FUNDING NUMBERS	
6. AUTHOR(S) U.S. Army Corps of Engineers New England Division				
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) U.S. Army Corps of Engineers, New England Division 424 Trapelo Road Waltham, MA 02254-9149			8. PERFORMING ORGANIZATION REPORT NUMBER	
9. SPONSORING / MONITORING AGENCY NAME(S) AND ADDRESS(ES) Connecticut Department of Environmental Protection Coastal Resources Management Division			10. SPONSORING / MONITORING AGENCY REPORT NUMBER	
11. SUPPLEMENTARY NOTES				
12a. DISTRIBUTION / AVAILABILITY STATEMENT Approved for public release Distribution is unlimited			12b. DISTRIBUTION CODE	
13. ABSTRACT (Maximum 400 words) This Appendix S report contains data gathered during Phase III of the ongoing project to inventory erosion and flood control structures on the northern shore of Long Island Sound within the statutory boundaries of the State of Connecticut. Included are the record of information on each structure and photographs for each structure.				
14. SUBJECT TERMS Glenville Quadrangle; coastal regions; structures			15. NUMBER OF PAGES 42	
			16. PRICE CODE	
17. SECURITY CLASSIFICATION OF REPORT Unclassified	18. SECURITY CLASSIFICATION OF THIS PAGE Unclassified	19. SECURITY CLASSIFICATION OF ABSTRACT Unclassified	20. LIMITATION OF ABSTRACT	

GENERAL INSTRUCTIONS FOR COMPLETING SF 298

The Report Documentation Page (RDP) is used in announcing and cataloging reports. It is important that this information be consistent with the rest of the report, particularly the cover and title page. Instructions for filling in each block of the form follow. It is important to *stay within the lines* to meet optical scanning requirements.

Block 1. Agency Use Only (Leave blank).

Block 2. Report Date. Full publication date including day, month, and year, if available (e.g. 1 Jan 88). Must cite at least the year.

Block 3. Type of Report and Dates Covered. State whether report is interim, final, etc. If applicable, enter inclusive report dates (e.g. 10 Jun 87 - 30 Jun 88).

Block 4. Title and Subtitle. A title is taken from the part of the report that provides the most meaningful and complete information. When a report is prepared in more than one volume, repeat the primary title, add volume number, and include subtitle for the specific volume. On classified documents enter the title classification in parentheses.

Block 5. Funding Numbers. To include contract and grant numbers; may include program element number(s), project number(s), task number(s), and work unit number(s). Use the following labels:

C - Contract	PR - Project
G - Grant	TA - Task
PE - Program	WU - Work Unit
Element	Accession No.

Block 6. Author(s). Name(s) of person(s) responsible for writing the report, performing the research, or credited with the content of the report. If editor or compiler, this should follow the name(s).

Block 7. Performing Organization Name(s) and Address(es). Self-explanatory.

Block 8. Performing Organization Report Number. Enter the unique alphanumeric report number(s) assigned by the organization performing the report.

Block 9. Sponsoring/Monitoring Agency Name(s) and Address(es). Self-explanatory.

Block 10. Sponsoring/Monitoring Agency Report Number. (If known)

Block 11. Supplementary Notes. Enter information not included elsewhere such as: Prepared in cooperation with...; Trans. of...; To be published in.... When a report is revised, include a statement whether the new report supersedes or supplements the older report.

Block 12a. Distribution/Availability Statement. Denotes public availability or limitations. Cite any availability to the public. Enter additional limitations or special markings in all capitals (e.g. NOFORN, REL, ITAR).

DOD - See DoDD 5230.24, "Distribution Statements on Technical Documents."

DOE - See authorities.

NASA - See Handbook NHB 2200.2.

NTIS - Leave blank.

Block 12b. Distribution Code.

DOD - Leave blank.

DOE - Enter DOE distribution categories from the Standard Distribution for Unclassified Scientific and Technical Reports.

NASA - Leave blank.

NTIS - Leave blank.

Block 13. Abstract. Include a brief (Maximum 200 words) factual summary of the most significant information contained in the report.

Block 14. Subject Terms. Keywords or phrases identifying major subjects in the report.

Block 15. Number of Pages. Enter the total number of pages.

Block 16. Price Code. Enter appropriate price code (NTIS only).

Blocks 17. - 19. Security Classifications. Self-explanatory. Enter U.S. Security Classification in accordance with U.S. Security Regulations (i.e., UNCLASSIFIED). If form contains classified information, stamp classification on the top and bottom of the page.

Block 20. Limitation of Abstract. This block must be completed to assign a limitation to the abstract. Enter either UL (unlimited) or SAR (same as report). An entry in this block is necessary if the abstract is to be limited. If blank, the abstract is assumed to be unlimited.

SECTION 22
CONNECTICUT COASTAL STRUCTURES INVENTORY STUDY
PHASE III

APPENDIX S
GLENVILLE QUADRANGLE

RECORDS OF STRUCTURES WITH PHOTOGRAPHS

DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
WALTHAM, MASSACHUSETTS

INVENTORY NUMBER: 1.00

QUAD : GLENVILLE
ADDRESS: 100 ARCH STREET
TOWN : GREENWICH STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : SEPARATES LAND AND WATER
MATERIAL : STONE IN CEMENT

DESCRIPTION

L(FT)= 2,000
W(FT)= 2-3.5
H(FT ABOVE MHW)= 3.5-4

INSPECTION DATE : 09/25/89 INSPECTION TIME: 1740

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : ROGER SHERMAN BALDWIN PK
ACCESS : PUBLIC PARK
LAND USE : RECREATIONAL

- PHOTOS -

#1 ROLL 135 NEG#12 LOOKING NORTHWEST
#2
#3
#4
#5

COMMENTS

STONE IN CEMENT UPPER PORTION
BOULBERS/SLABS LOWER PORTION

INVENTORY NUMBER: 2.00

QUAD : GLENVILLE
ADDRESS: GRASS ISLAND ROAD
TOWN : GREENWICH STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: RIPRAP CONDITION: POOR
MAIN FUNCTION : PROTECTIVE LAYER WHICH PREVENTS EROSION OF A SLOPE
MATERIAL : BOULDERS & FRAG

DESCRIPTION

L(FT)= 300
W(FT)= N/A
H(FT ABOVE MHW)= 2-3

INSPECTION DATE : 09/26/89 INSPECTION TIME: 1245

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PUBLIC; TOWN DOCK
ACCESS : PUBLIC
LAND USE : RECREATIONAL

- PHOTOS -

#1 ROLL 135 NEG#14 LOOKING WEST
#2
#3
#4
#5

COMMENTS

RIPRAP LOCATED NORTH OF NORTH DOCK

INVENTORY NUMBER: 3.00

QUAD : GLENVILLE
ADDRESS: GRASS ISLAND ROAD
TOWN : GREENWICH STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : SEPARATES LAND AND WATER, RETAINS LAND
MATERIAL : STONES/BOULDERS

DESCRIPTION

L(FT)= 422
W(FT)= 2
H(FT ABOVE MHW)= 1.5-2.5

INSPECTION DATE : 09/26/89 INSPECTION TIME: 1250

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PUBLIC; NORTH TOWN DOCK
ACCESS : PUBLIC
LAND USE : RECREATIONAL

- PHOTOS -

#1 ROLL 135 NEG#15 LOOKING WEST
#2
#3
#4
#5

COMMENTS

NORTH OF NORTH DOCK, SECTIONS WITH CONCRETE
SOUTH OF NORTH DOCK, NO CONCRETE

INVENTORY NUMBER: 4.00

QUAD : GLENVILLE
ADDRESS: GRASS ISLAND ROAD
TOWN : GREENWICH STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: RIPRAP CONDITION: FAIR
MAIN FUNCTION : PROTECTIVE LAYER WHICH PREVENTS EROSION OF A SLOPE
MATERIAL : LARGE BOULDERS

DESCRIPTION

L(FT)= 115
W(FT)= N/A
H(FT ABOVE MHW)= 5

INSPECTION DATE : 09/26/89 INSPECTION TIME: 1255

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PUBLIC; TOWN DOCK
ACCESS : PUBLIC
LAND USE : RECREATIONAL

- PHOTOS -

#1 ROLL 135 NEG#16 LOOKING WEST
#2
#3
#4
#5

COMMENTS

RIPRAP MISSING SOUTH OF NORTH DOCK IN FRONT OF AN OLD DOCK
BULKHEAD

INVENTORY NUMBER: 5.00

QUAD : GLENVILLE
ADDRESS: GRASS ISLAND ROAD
TOWN : GREENWICH STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : SEPARATES LAND AND WATER, RETAINS LAND
MATERIAL : STONE

DESCRIPTION

L(FT)= 175
W(FT)= 2-5
H(FT ABOVE MHW)= 3

INSPECTION DATE : 09/26/89 INSPECTION TIME: 1300

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PUBLIC; SOUTH TOWN DOCK
ACCESS : PUBLIC
LAND USE : RECREATIONAL

- PHOTOS -

#1 ROLL 135 NEG#17 LOOKING WEST
#2 ROLL 135 NEG#18 LOOKING WEST
#3
#4
#5

COMMENTS

NORTH OF THE SOUTH DOCK THE SEAWALL IS CAPPED WITH 4"-6" OF
STONE IN CONCRETE

INVENTORY NUMBER: 6.00

QUAD : GLENVILLE
ADDRESS: GRASS ISLAND ROAD
TOWN : GREENWICH STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: RIPRAP CONDITION: GOOD-POOR
MAIN FUNCTION : PROTECTIVE LAYER WHICH PREVENTS EROSION OF A SLOPE
MATERIAL : BOULDERS & FRAG

DESCRIPTION

L(FT)= 650
W(FT)= N/A
H(FT ABOVE MHW)= 6

INSPECTION DATE : 09/26/89 INSPECTION TIME: 1320

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : GREENWICH BOAT & YCT CLB
ACCESS : PRIVATE
LAND USE : RECREATIONAL/COMMERCIAL

- PHOTOS -

#1 ROLL 135 NEG#19 LOOKING NORTHEAST
#2
#3
#4
#5

COMMENTS

CONDITIONS RANGES FROM GOOD-LARGE BOULDERS(45 DEG) TO POOR-
STONES ARE BROKEN, WORN DOWN AND BANK IS FALLING INTO
WATER(90 DEG)

INVENTORY NUMBER: 7.00

QUAD : GLENVILLE
ADDRESS: SMITH ROAD
TOWN : GREENWICH STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD-FAIR
MAIN FUNCTION : SEPARATES LAND AND WATER, RETAINS LAND
MATERIAL : STONE IN CEMENT

DESCRIPTION

L(FT)= 2,000
W(FT)= 3
H(FT ABOVE MHW)= 4

INSPECTION DATE : 09/26/89 INSPECTION TIME: 1630

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 135 NEG#20 LOOKING SOUTH ACROSS CHANNEL (YACHT CLUB)
#2 ROLL 136 NEG#7 LOOKING SOUTHEAST
#3
#4
#5

COMMENTS

PERMIT #69-316; 60' EXTENSION TO ORIGINAL SEAWALL

INVENTORY NUMBER: 7.10

QUAD : GLENVILLE
ADDRESS: DEAN LANE
TOWN : GREENWICH
COUNTY : FAIRFIELD

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL&RIPRAP CONDITION: GOOD
MAIN FUNCTION : SEPARATES LAND AND WATER & PREVENTS EROSION OF A S
MATERIAL : STONE

DESCRIPTION

L(FT)= 1,200
W(FT)= UNKNOWN
H(FT ABOVE MHW)= UNKNOWN

INSPECTION DATE : 09/26/89 INSPECTION TIME: 1820

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 136 NEG#8 LOOKING SOUTHEAST
#2
#3
#4
#5

COMMENTS

COULD NOT ACCESS
RIPRAP AROUND LAND PROTRUSION; SEAWALL ON NOTHERN PORTION IN
AREA OF DOCK

INVENTORY NUMBER: 8.00

QUAD : GLENVILLE
ADDRESS: FIELD POINT CIRCLE
TOWN : GREENWICH STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : SEPARATES LAND AND WATER, RETAINS LAND
MATERIAL : STONE IN CEMENT

DESCRIPTION

L(FT)= 250
W(FT)= 2
H(FT ABOVE MHW)= 11

INSPECTION DATE : 09/26/89 INSPECTION TIME: 1505

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 135 NEG#21 LOOKING EAST
#2
#3
#4
#5

COMMENTS

INVENTORY NUMBER: 9.00

QUAD : GLENNVILLE
ADDRESS: FIELD POINT CIRCLE
TOWN : GREENWICH STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BREAKWATER CONDITION: GOOD
MAIN FUNCTION : PROTECTS HARBOR/ANCHORAGE BY INTERCEPTING WAVES
MATERIAL : CEMENT BLOCKS

DESCRIPTION

L(FT)= 100
W(FT)= 12
H(FT ABOVE MHW)= 6

INSPECTION DATE : 09/26/89 INSPECTION TIME: 1510

- LAND CLASSIFICATION -

PERMIT NUMBER: 65234
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 135 NEG#22 LOOKING WEST
#2
#3
#4
#5

COMMENTS

SANDY WITH SOME COBBLES

INVENTORY NUMBER: 10.00

QUAD : GLENVILLE
ADDRESS: FIELD POINT CIRCLE
TOWN : GREENWICH STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : SEPARATES LAND AND WATER, RETAINS LAND
MATERIAL : CONCRETE

DESCRIPTION

L(FT)= 154
W(FT)= 1
H(FT ABOVE MHW)= 8

INSPECTION DATE : 09/26/89 INSPECTION TIME: 1515

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 135 NEG#23 LOOKING EAST
#2
#3
#4
#5

COMMENTS

STONES ALONG TOE

INVENTORY NUMBER: 11.00

QUAD : GLENVILLE
ADDRESS: FIELD POINT CIRCLE
TOWN : GREENWICH STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BREAKWATER CONDITION: GOOD
MAIN FUNCTION : PROTECTS HARBOR/ANCHORAGE BY INTERCEPTING WAVES
MATERIAL : STONE IN CEMENT

DESCRIPTION

L(FT)= 150
W(FT)= 10
H(FT ABOVE MHW)= 15

INSPECTION DATE : 09/26/89 INSPECTION TIME: 1515

- LAND CLASSIFICATION -

PERMIT NUMBER: 55198
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 135 NEG#24 LOOKING SOUTH
#2
#3
#4
#5

COMMENTS

COBBLED SHORE
PERMIT #55-198 WAS FOR BREAKWATER 6' ABOVE MHW
PERMIT #65-229 EXPANDED BREAKWATER TO 15' ABOVE MHW

INVENTORY NUMBER: 12.00

QUAD : GLENVILLE
ADDRESS: 70,80,84 FIELD POINT ROAD
TOWN : GREENWICH STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : SEPARATES LAND AND WATER, RETAINS LAND
MATERIAL : STONE IN CEMENT

DESCRIPTION

L(FT)= 756
W(FT)= 2
H(FT ABOVE MHW)= 16

INSPECTION DATE : 09/26/89 INSPECTION TIME: 1725

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 136 NEG#4 LOOKING WEST
#2 ROLL 136 NEG#5 LOOKING WEST
#3 ROLL 136 NEG#6 LOOKING NORTHEAST
#4
#5

COMMENTS

PORTION OF WALL IS STONE IN CEMENT & PORTION IS STONE
COBBLE AND STONE BEACH

INVENTORY NUMBER: 13.00

QUAD : GLENVILLE
ADDRESS: 34,40,50 FAIRFIELD PT RD
TOWN : GREENWICH STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : SEPARATES LAND AND WATER, RETAINS LAND
MATERIAL : STONE IN CEMENT

DESCRIPTION

L(FT)= 744
W(FT)= 2 LOT #50, 4 LOT #34 & #40
H(FT ABOVE MHW)= 4.5

INSPECTION DATE : 09/26/89 INSPECTION TIME: 1625

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 136 NEG# 1 LOOKING NORTHEAST
#2
#3
#4
#5

COMMENTS

COBBLE BEACH

INVENTORY NUMBER: 14.00

QUAD : GLENVILLE
ADDRESS: GLENWOOD DRIVE
TOWN : GREENWICH STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : SEPARATES LAND AND WATER
MATERIAL : STONE IN CEMENT

DESCRIPTION

L(FT)= 607 ALONG SHORELINE THEN 113 INLAND
W(FT)= 2
H(FT ABOVE MHW)= 7

INSPECTION DATE : 09/26/89 INSPECTION TIME: 1700

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PUBLIC
ACCESS : PUBLIC
LAND USE : RECREATIONAL

- PHOTOS -

#1 ROLL 136 NEG#2 LOOKING SOUTHEAST
#2 ROLL 136 NEG#3 LOOKING SOUTHEAST
#3
#4
#5

COMMENTS

INVENTORY NUMBER: 15.00

QUAD : GLENVILLE
ADDRESS: GLENWOOD DRIVE
TOWN : GREENWICH
COUNTY : FAIRFIELD

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : SEPARATES LAND AND WATER, RETAINS LAND
MATERIAL : STONE IN CEMENT

DESCRIPTION

L(FT)= 305
W(FT)= 2
H(FT ABOVE MHW)= 5

INSPECTION DATE : 09/27/89 INSPECTION TIME: 845

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : BELLE HAVEN YACHT CLUB
ACCESS : PRIVATE
LAND USE : RECREATIONAL & COMMERCIAL

- PHOTOS -

#1 ROLL 136 NEG#10 LOOKING NORTHWEST
#2
#3
#4
#5

COMMENTS

SEAWALL SURROUNDS FRONT (EAST) AND SIDE (SOUTH) SIDES OF THE
PROPERTY

INVENTORY NUMBER: 16.00

QUAD : GLENVILLE
ADDRESS: GLINWOOD DRIVE
TOWN : GREENWICH STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BREAKWATER CONDITION: GOOD
MAIN FUNCTION : PROTECTS ANCHORAGE BY INTERCEPTING WAVES
MATERIAL : LARGE BOULDERS

DESCRIPTION

L(FT)= 230
W(FT)= 11
H(FT ABOVE MHW)= 3

INSPECTION DATE : 09/27/89 INSPECTION TIME: 850

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : BELLE HAVEN YACHT CLUB
ACCESS : PRIVATE
LAND USE : RECREATIONAL & COMMERCIAL

- PHOTOS -

#1 ROLL 136 NEG#11 LOOKING EAST
#2
#3
#4
#5

COMMENTS

EXTENDS FROM SOUTHEAST CORNER OF SEAWALL, INVENTORY #15

INVENTORY NUMBER: 17.00

QUAD : GLENVILLE
ADDRESS: GLENWOOD DRIVE
TOWN : GREENWICH STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL&RIPRAP CONDITION: GOOD
MAIN FUNCTION : SEPARATES LAND AND WATER, PREVENTS EROSION OF A SL
MATERIAL : LARGE BOULDERS

DESCRIPTION

L(FT)= 160
W(FT)= 3.6
H(FT ABOVE MHW)= 6

INSPECTION DATE : 09/27/89 INSPECTION TIME: 835

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : BELLE HAVEN YACHT CLUB
ACCESS : PRIVATE
LAND USE : RECREATIONAL & COMMERCIAL

- PHOTOS -

#1 ROLL 136 NEG#9 LOOKING SOUTH WEST
#2
#3
#4
#5

COMMENTS

SEAWALL WITH RIPRAP WATERWARD

INVENTORY NUMBER: 18.00

QUAD : GLENVILLE
ADDRESS: GLENWOOD DRIVE
TOWN : GREENWICH STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : SEPARATES LAND AND WATER
MATERIAL : STONE IN CEMENT

DESCRIPTION

L(FT)= 200
W(FT)= 2
H(FT ABOVE MHW)= 6

INSPECTION DATE : 09/27/89 INSPECTION TIME: 855

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 136 NEG#12 LOOKING NORTHWEST
#2
#3
#4
#5

COMMENTS

STONES AT TOE

INVENTORY NUMBER: 19.00

QUAD : GLENVILLE
ADDRESS: 290 OTTER ROCK ROAD
TOWN : GREENWICH STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL&RIPRAP CONDITION: GOOD
MAIN FUNCTION : SEPARATES LAND & WATER, RETAINS LAND, PREVENTS WAL
MATERIAL : STONE IN CEMENT

DESCRIPTION

L(FT)= 578
W(FT)= 10
H(FT ABOVE MHW)= 3

INSPECTION DATE : 09/27/89 INSPECTION TIME: 910

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 136 NEG#13 LOOKING NORTHEAST
#2
#3
#4
#5

COMMENTS

CONCRETE CAP ON SEAWALL UNTIL BREAKWATER INVENTORY #20, THEN
SLATE CAP

INVENTORY NUMBER: 20.00

QUAD : GLENVILLE
ADDRESS: 290 OTTER ROCK ROAD
TOWN : GREENWICH STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BREAKWATER CONDITION: GOOD
MAIN FUNCTION : PROTECTS ANCHORAGE BY INTERCEPTING WAVES
MATERIAL : CONCRETE&BOULD

DESCRIPTION

L(FT)= 225
W(FT)= 7
H(FT ABOVE MHW)= 1.3

INSPECTION DATE : 09/27/89 INSPECTION TIME: 925

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 136 NEG#14 LOOKING SOUTHEAST
#2
#3
#4
#5

COMMENTS

INVENTORY NUMBER: 21.00

QUAD : GLENVILLE
ADDRESS: 74 HARBOR DRIVE
TOWN : GREENWICH STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : SEPARATES LAND AND WATER
MATERIAL : STONE IN CEMENT

DESCRIPTION

L(FT)= 4,000
W(FT)= 1.5-2.6
H(FT ABOVE MHW)= 2.8-10

INSPECTION DATE : 09/27/89 INSPECTION TIME: 1015

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 136 NEG#15 LOOKING NORTH
#2 ROLL 136 NEG#16 LOOKING SOUTHWEST
#3 ROLL 136 NEG#17 LOOKING NORTH
#4 ROLL 136 NEG#18 LOOKING SOUTH
#5

COMMENTS

WEST BANK OF BYRAM HARBOR
SEAWALL STARTS AT 74 HARBOR DRIVE CONTINUES ALONG BYRAM ROAD
TO ONE ISLAND ROAD WHERE SHORELINE IS RIPRAP COVERED

INVENTORY NUMBER: 22.00

QUAD : GLENVILLE
ADDRESS: RITCH AVENUE
TOWN : GREENWICH STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : SEPARATES LAND AND WATER, RETAINS LAND
MATERIAL : STONE IN CEMENT

DESCRIPTION

L(FT)= 1,800
W(FT)= 1.6
H(FT ABOVE MHW)= 3.5-6.2

INSPECTION DATE : 09/27/89 INSPECTION TIME: 1145

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 136 NEG#19 LOOKING NORTHWEST
#2
#3
#4
#5

COMMENTS

INVENTORY NUMBER: 23.00

QUAD : GLENVILLE
ADDRESS: RITCH AVENUE
TOWN : GREENWICH STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: GROIN CONDITION: GOOD
MAIN FUNCTION : TRAPS LITTORAL DRIFT, RETARDS SHORE EROSION
MATERIAL : STONE IN CEMENT

DESCRIPTION

L(FT)= 108
W(FT)= 10.5
H(FT ABOVE MHW)= 2.5

INSPECTION DATE : 09/27/89 INSPECTION TIME: 1150

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PUBLIC; BYRAM PARK
ACCESS : PUBLIC
LAND USE : RECREATIONAL

- PHOTOS -

#1 ROLL 136 NEG#20 LOOKING SOUTH
#2
#3
#4
#5

COMMENTS

SANDY BEACH AREA

INVENTORY NUMBER: 24.00

QUAD : GLENVILLE
ADDRESS: RITCH AVENUE
TOWN : GREENWICH
COUNTY : FAIRFIELD
STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: GROIN
MAIN FUNCTION : TRAPS LITTORAL DRIFT, RETARDS SHORE EROSION
MATERIAL : STONE IN CEMENT
CONDITION: FAIR

DESCRIPTION

L(FT)= 29
W(FT)= 5.5
H(FT ABOVE MHW)= 2

INSPECTION DATE : 09/27/89 INSPECTION TIME: 1205

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PUBLIC; BYRAM PARK
ACCESS : PUBLIC
LAND USE : RECREATIONAL

- PHOTOS -

#1 ROLL 136 NEG#21 LOOKING SOUTH
#2
#3
#4
#5

COMMENTS

SANDY BEACH AREA

INVENTORY NUMBER: 25.00

QUAD : GLENVILLE
ADDRESS: RITCH AVENUE
TOWN : GREENWICH STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: FAIR
MAIN FUNCTION : SEPARATES LAND AND WATER, RETAINS LAND
MATERIAL : STONE

DESCRIPTION

L(FT)= 674
W(FT)= 2-5.5
H(FT ABOVE MHW)= 2,5

INSPECTION DATE : 09/27/89 INSPECTION TIME: 1210

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PUBLIC; BYRAM PARK &
ACCESS : BYRAM SHORE BOAT CLUB
LAND USE : RECREATIONAL

- PHOTOS -

#1 ROLL 136 NEG#22 LOOKING SOUTH
#2
#3
#4
#5

COMMENTS

STONE IN CEMENT UPPER 1 FOOT, REST IS STONE

INVENTORY NUMBER: 26.00

QUAD : GLENVILLE
ADDRESS: GAMECOCK ROAD
TOWN : GREENWICH STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD-FAIR
MAIN FUNCTION : SEPARATES LAND AND WATER, RETAINS LAND
MATERIAL : STONE

DESCRIPTION

L(FT) = 492
W(FT) = 1.7
H(FT ABOVE MHW) = 7

INSPECTION DATE : 09/27/89 INSPECTION TIME: 1500

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 136 NEG#23 LOOKING SOUTH
#2 ROLL 136 NEG#24 LOOKING SOUTH
#3
#4
#5

COMMENTS

STONE IN CEMENT UPPER 2 FEET
SOME AREAS IN NEED OF REPAIR

INVENTORY NUMBER: 27.00

QUAD : GLENVILLE
ADDRESS: GAMECOCK ROAD
TOWN : GREENWICH STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : SEPARATES LAND AND WATER, RETAINS LAND
MATERIAL : STONE/BOULDERS

DESCRIPTION

L(FT)= 708
W(FT)= 2
H(FT ABOVE MHW)= 5.7-7.5

INSPECTION DATE : 09/27/89 INSPECTION TIME: 1515

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 137 NEG#1 LOOKING WEST
#2 ROLL 137 NEG#2 LOOKING WEST
#3 ROLL 137 NEG#3 LOOKING WEST
#4
#5

COMMENTS

SEAWALL OFTEN CAPPED WITH 3' HIGH EXTENSION

INVENTORY NUMBER: 28.00

QUAD : GLENVILLE
ADDRESS: GAMECOCK ROAD
TOWN : GREENWICH STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD-FAIR
MAIN FUNCTION : SEPARATES LAND AND WATER, RETAINS LAND
MATERIAL : STONE

DESCRIPTION

L(FT)= 2,098
W(FT)= 3.4
H(FT ABOVE MHW)= 4.1-6

INSPECTION DATE : 09/27/89 INSPECTION TIME: 1530

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 137 NEG#4 LOOKING WEST (STONE BLOCKS)
#2 ROLL 137 NEG#5 LOOKING NORTHWEST (STONE BLOCKS)
#3 ROLL 137 NEG#6 LOOKING NORTH (STONE IN CEMENT)
#4
#5

COMMENTS

UPPER SEAWALL OFTEN STONE IN CEMENT, LOWER IS BOULDERS
ONE SECTION IN SOUTHERN PART OF WALL IS STONE BLOCKS
SOME AREAS STONE IN CEMENT THROUGHOUT

GL 1.00 #1




GL 2.00 #1




S30

GL 3.00 #1




GL 4.00 #1



GL 5.00 #1



GL 5.00 #2




GL 6.00 #1



GL 7.00 #1



GL 7.00 #2



GL 7.10 #1



GL 8.00 #1




GL 9.00 #1




GL 10.00 #1




GL 11.00 #1




GL 12.00 #1




GL 12.00 #2




GL 12.00 #3




GL 13.00 #1



GL 14.00 #1




GL 14.00 #2



GL 15.00 #1




GL 16.00 #1




GL 17.00 #1




GL 18.00 #1




GL 19.00 #1



GL 20.00 #1



GL 21.00 #1




GL 21.00 #2



GL 21.00 #3




GL 21.00 #4




GL 22.00 #1




GL 23.00 #1




GL 24.00 #1



GL 25.00 #1




GL 26.00 #1




GL 26.00 #2



GL 27.00 #1



GL 27.00 #2




GL 27.00 #3



GL 28.00 #1



GL 28.00 #2



GL 28.00 #3

